Maryland Historical Trust

men

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust MHT Number AL-II-A-145

Name and SHA No. Dolly Road over Flintstone Creek/A10400 (A10410)
<u>Location:</u> Street/Road Name and Number: <u>Dolly Road</u>
City/Town: Flintstone Vicinity x
County: Allegany
Ownership: _State_x_County_Municipal_Other
This bridge projects over: _Road_Railwayx Water_Land
Is the bridge located within a designated district: yes x no
_NR listed district_NR determined eligible district _locally designated_other Name of District
Bridge Type:
_Timber BridgeBeam Bridge_Truss-Covered_TrestleTimber-and-Concrete
_Stone Arch
_Metal Truss
_Movable BridgeSwingBascule Single Leaf_Bascule Multiple LeafVertical LiftRetractilePontoon
<u>x</u> Metal Girder <u>x</u> Rolled GirderRolled Girder Concrete Encased Plate GirderPlate Girder Concrete Encased

_Metal Suspension
_Metal Arch
_Metal Cantilever
_Concrete
_Concrete Arch _Concrete Slab_Concrete Beam
_Rigid Frame
_Other Type Name

Description:

Describe Setting: A10400 (A10410) carries Dolly Road over Flintstone Creek in Allegany County, Maryland. Dolly Road runs generally east-west at this location; Flintstone Creek flows generally north-south. The bridge is located in a rural wooded area no structures in view. Flintstone Creek has a wooded channel bank in this area.

Describe Superstructure and Substructure: The superstructure is a single span steel multi-beam bridge with an open grid metal deck, metal curb and W-beam guardrails with metal channel posts mounted to the exterior beam. The span length is 23', and the total bridge length is 30'. The superstructure is in good condition and no major repairs were recommended. The substructure is reinforced concrete abutments and wing walls. There is laid field stone along the banks to act as a retaining wall. There is some scour on the abutments and slight undermining at the water level.

Discuss Major Alterations: According to the 1993 county inspection report, "major rehabs are reported to have occurred [to bridge A10400 (A10410)] in 1972. There is no documentary evidence in the files to explain what this rehab entailed. In 1988, the timber deck and curbs were replaced the cracked and spalled areas on the north abutment were filled with grout, rip rap was placed around the base of the abutments on the bank and the guardrails were modified to meet current standards.

History:

When Built: 1930

Why Built: local transportation needs

Who Built:

Why Altered: structural improvements and safety needs

Was this bridge built as part of an organized bridge building campaign: originally yes

Surveyor Analysis:

This bridge may have NR significance for association with:

A Events Person

C Engineering/Architectural

Was this bridge constructed in response to significant events in Maryland or local history: no

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area: no

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district: no

Is the bridge a significant example of its type: no

Does the bridge retain integrity of the important elements described in the Context Addendum: It is likely that the 1972 "major rehab" involved alteration and replacement of the superstructure, as well as repairs to the abutments. In 1988, the deck was replaced and repairs were made to the abutments. The substructure does retain some of its original CDE's; however, because of extensive alterations made tot he superstructure (involving primary and secondary CDE modifications) the bridge does not retain its integrity.

Is the bridge a significant example of the work of the manufacturer, designer, and/or engineer and why: no

Should this bridge be given further study before significance analysis is made and why: Further study is not warranted for A10400 (A10410) because of extensive structural alterations.

Bibliography:

Allegany County

v.d. Bridge Inspection Files

Greiner, Inc.

1995 Historic Bridge Inventory Form

Spero, P.A.C. & Company, and Louis Berger & Associates

1994 Historic Bridges in Maryland: Historic Bridge Context

United States Geological Survey


1950, 7.5' Flintstone Quadrangle, photorevised 1974

Surveyor:

Name: Stephanie L. Bandy Date: September 1995

Organization: State Highway Admin. Telephone: (410) 321-2213

Address: 2323 West Joppa Road Brooklandville, MD 21022





BR# 20A10410 (A 10400)

AL-II-A-145

FLINTSIONE CREEK

ALLEGANY (O, MD)

DAVID KING

2/3/95

SHA

EAST APPROACH

10F4



AL-II-A-145

BR = 20A10410 (A 10400)

FLINTSTONE CREEK

ALLEGANY (O., MD


DAVID KING

2/3/95

5 H A

2 OF 4

WEST APPROACH



BR# 20A10410 (A10400) AL-II-A- 145 FLINTSTONE CREEK ALLEGANY CO., MID DAVID KING 2/3/95 S. H.A NORTH ELEVATION (FOUNSTREAM)

3 OF 4



BR# 20A10410 (A-10400) AL-II- A- 145 FLINTSTONE CREEK ALLEGANY CO., MD DAVID KING 2/3/95 SHA SOUTH ELEVATION (UPSTREAM)

4 OF 4